

**ENVIRONMENTAL PROTECTION
REPORT – VAPOUR RECOVERY**

APPENDIX 1

Premise Shell st lves Person Seen Mr Komal
Address Pennery rd st lves, PE275RG

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

Double VRI inspection conducted by N.P. Shepley on behalf
Penhryn District Council. Please see recheck notice.

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS
AND ASSOCIATED LOG BOOK**

Inspected Y/N Satisfactory Y/N

Notes:

No incidents

**d) TESTING CERTIFICATE FOR PRESSURE RELIEF
VALVES (Annual)**

Inspected Y/N Satisfactory Y/N

Notes:

Expired - copy of new
certificate to be forwarded
to me

**b) LOG BOOK DETAILING MAINTENANCE,
EXAMINATION & TESTING, INVENTORY
CHECKING, INSTALLATION & REPAIR WORK
(SITE REGISTER)**

Inspected Y/N Satisfactory Y/N

Notes:

Nothing recorded.

e) STAFF COMPETENCE & TRAINING

No of Staff 5 No Questioned 1

Inspected Y/N Satisfactory Y/N

Notes:

**c) VAPOUR RECOVERY CONNECTIONS &
SIGNS**

Inspected Y/N Satisfactory Y/N

Notes:

Does the site have stage II vapour recovery? Y/N

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes:

Site register to be organised

Are procedures in place adequate in the event of any leaks
or spillages? Y/N

Notes:

Inspector Shepley Date 16th March 2011

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation