

**ENVIRONMENTAL PROTECTION
REPORT - VAPOUR RECOVERY**

APPENDIX 1

Premise Godmanchester Service St Person Seen Karen Barnfield
Address Cardinal Way Godmanchester Huntingdon PE29 2XN

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

Inspection conducted by H.R. Shepherd on behalf of Huntingdon District Council.

a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK

Inspected Y/N Satisfactory Y/N

Notes:

No incidents recorded

d) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES (Annual)

Inspected Y/N Satisfactory Y/N

Notes:

*Not seen - to be forwarded
Maintenance of pipe & tank
installations 10/05/11*

b) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)

Inspected Y/N Satisfactory Y/N

Notes:

No incidents recorded

e) STAFF COMPETENCE & TRAINING

No of Staff ☒ Managers ☒

No Questioned ☐

Inspected Y/N Satisfactory Y/N

Notes:

2 competent - DCD box

c) VAPOUR RECOVERY CONNECTIONS & SIGNS

Inspected ☒ Y/N Satisfactory ☒ Y/N

Notes:

Does the site have stage II vapour recovery? ☒ Y/N

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory ☒ Y/N

Notes:

Are procedures in place adequate in the event of any leaks or spillages? ☒ Y/N

Notes:

Inspector H.R. SHEPHERD Date 07/02/12

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.

Contract for the conduct of process permits: HDC & CCC

Copy of VR cert received 23/02/12