

**ENVIRONMENTAL PROTECTION
REPORT - VAPOUR RECOVERY**

Premises Edmondeston service station Person Seen Arul

Address Logan Way Edmondeston PE29 2XH

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

Vapour recovery inspection completed by H. Steptoe Cambridge
County Council on behalf of Rushdown District Council

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS
AND ASSOCIATED LOG BOOK**

Inspected Y/N Satisfactory Y/N

Notes:

Nothing documented

**b) TESTING CERTIFICATE FOR PRESSURE RELIEF
VALVES**

Inspected Y/N Satisfactory Y/N

Notes:

Not seen
Recheck when advice issued
Revisit tel con' - still not available on
28/01/14.

**c) LOG BOOK DETAILING MAINTENANCE,
EXAMINATION & TESTING, INVENTORY
CHECKING, INSTALLATION & REPAIR WORK
(SITE REGISTER)**

Inspected Y/N Satisfactory Y/N

Notes:

Section to be made in
site register. Maintenance
docs kept separately

d) STAFF COMPETENCE & TRAINING

No of Staff 67 No Questioned 1

Inspected Y/N

Satisfactory Y/N

Notes:

All signed off as competent

**e) VAPOUR RECOVERY CONNECTIONS &
SIGNS**

Inspected Y/N Satisfactory Y/N

Notes:

Does the site have stage II vapour recovery? Y/N

Notes:

Noting examines stage II
(Area manager)

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes:

Shell

Are procedures in place adequate in the event of any leaks
or spillages? Y/N

Notes:

No per Risk assessment.

Signed [Signature]

Tel /Email 01954 280 628

Received by [Signature]

Date/Time 31/07/13

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.

Received email 28/01/14 with copy of VR inspection cert.