

**ENVIRONMENTAL PROTECTION  
REPORT – VAPOUR RECOVERY**

**APPENDIX 1**

Premise Pace St lves Person Seen Mr A Thangam  
Address Woolwich rd, St lves PE27 5UN

**OBSERVATIONS, ADVICE AND RECOMMENDATIONS:**

As a result of the inspection of your premises your attention is drawn to the following matters:

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS  
AND ASSOCIATED LOG BOOK**

Inspected Y/N Satisfactory Y/N

Notes:

No incidents

**d) TESTING CERTIFICATE FOR PRESSURE RELIEF  
VALVES (Annual)**

Inspected Y/N Satisfactory Y/N

Notes:

20/07/09

**b) LOG BOOK DETAILING MAINTENANCE,  
EXAMINATION & TESTING, INVENTORY  
CHECKING, INSTALLATION & REPAIR WORK  
(SITE REGISTER)**

Inspected Y/N Satisfactory Y/N

Notes:

No incidents

**e) STAFF COMPETENCE & TRAINING**

No of Staff 5 No Questioned 12

Inspected Y/N Satisfactory Y/N

Notes:

**c) VAPOUR RECOVERY CONNECTIONS &  
SIGNS**

Inspected Y/N Satisfactory Y/N

Notes:

VR sign req for tank 2

Does the site have stage II vapour recovery? Y/N

Notes:

**f) SITE MANAGEMENT & OTHER COMMENTS**

Satisfactory Y/N

Notes:

Are procedures in place adequate in the event of any leaks  
or spillages? Y/N

Notes:

Inspector [Signature] Date 1st Sept 2010

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.

Contract for the conduct of process permits: HDC & CCC

**ENVIRONMENTAL PROTECTION  
REPORT – VAPOUR RECOVERY**

APPENDIX 1

Premise Pace St Ives Person Seen \_\_\_\_\_  
Address Meedungworth Road St Ives Hunthorpe

**OBSERVATIONS, ADVICE AND RECOMMENDATIONS:**

As a result of the inspection of your premises your attention is drawn to the following matters:

received copy of VR inspection report premises brought into compliance

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK**

Inspected Y/N \_\_\_\_\_ Satisfactory Y/N \_\_\_\_\_

Notes:

N/A

**d) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES (Annual)**

Inspected ☒ Y/N \_\_\_\_\_ Satisfactory ☒ Y/N \_\_\_\_\_

Notes:

Date of next test 30/06/11.

**b) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)**

Inspected Y/N \_\_\_\_\_ Satisfactory Y/N \_\_\_\_\_

Notes:

N/A

**e) STAFF COMPETENCE & TRAINING**

No of Staff ☐ No Questioned ☐

Inspected Y/N \_\_\_\_\_ Satisfactory Y/N \_\_\_\_\_

Notes:

N/A

**c) VAPOUR RECOVERY CONNECTIONS & SIGNS**

Inspected Y/N \_\_\_\_\_ Satisfactory Y/N \_\_\_\_\_

Notes:

N/A

Does the site have stage II vapour recovery? Y/N \_\_\_\_\_

Notes:

N/A

**f) SITE MANAGEMENT & OTHER COMMENTS**

Satisfactory Y/N \_\_\_\_\_

Notes:

N/A

Are procedures in place adequate in the event of any leaks or spillages? Y/N \_\_\_\_\_

Notes:

N/A

Inspector Deborah Date 15/10/10

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation

## Vapour Recovery Inspection Test Certificate for Stage 1&2

Test Details					
Site Name	Pace St Ives				
Site Address	Needingworth Road, St Ives, Huntingdon				
Oil Company	Pace	Inspected By	S.Evans		
Date of Test	30/06/2010	Certificate No	100630UKSVRC	Test kit no	200263


Test Results			
	Pass/Fail/NA		Yes/No/NA
System Integrity	Pass	Type of Manifold (High/Low, Underground)	Low
P&V Valve Pressure test	Pass	Clean Flame Arrestor	Yes
P&V Valve Vacuum test	Pass	System Drain Down	N/a
P&V Valve Leak test	Pass	Petrol Tank Numbers	1,4
Number of P&V Valves	1	Diesel Tank Numbers	2,3,5
New P&V Valves fitted (Y/N)	No	Diesel Vents in manifold (Y/N)	No
Caps, Seals & Signage	Pass	If applicable which tank	N/a
Test Notes			
Overall Test Result Pass/Fail		Pass	
Type of Test	Full	Date of next test	30/06/11

We declare that on the date shown above the vapour recovery system was examined and tested in accordance with E&S's test protocol and procedures for periodic examination and testing. Subject to any conditions recorded above, certify that the vapour recovery system meet all legislation and recommendations.

Company Seal:

Note: This certificate is invalid unless correctly stamped with the E&S validation Mark and may not be reproduced without the express approval of E&S.

Signed:



Dated: 30/06/2010

Mark Willis-Operations Manager