

REPORT - VAPOUR RECOVERY

Premises Mathurst & Wals

Person Seen Mr Anton Thanasingham

Address Needling Rd, Pe 27 SWF

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

Inspection conducted on behalf of Kenburyda District Council
note being told 1st July 2013 to DP Main dealer group.

a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK

Inspected Y/N Satisfactory Y/N

Notes:

b) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES

Inspected Y/N Satisfactory Y/N

Notes: E2 S expires 22/06/13

c) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)

Inspected Y/N Satisfactory Y/N

Notes:

d) STAFF COMPETENCE & TRAINING

No of Staff 7 No Questioned 1

Inspected Y/N

Satisfactory Y/N

Notes:

e) VAPOUR RECOVERY CONNECTIONS & SIGNS

Inspected Y/N Satisfactory Y/N

Notes:

Does the site have stage II vapour recovery? Y/N

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes:

Are procedures in place adequate in the event of any leaks or spillages? Y/N

Notes: add site

Signed [Signature]

Tel /Email hannah.depled@cambridgeshire.gov.uk

Received by [Signature]

Date/Time 24/05/13

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.