

ENVIRONMENTAL PROTECTION REPORT - VAPOUR RECOVERY

APPENDIX 1

Premise Kings bre Garage Person Seen Mr V Scerabile
Address Hugobere St Necks PE19 1JZ

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK

Inspected Y/N

Satisfactory Y/N

Notes:

d) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES (Annual)

Inspected Y/N

Satisfactory Y/N

Notes:

FPI - due
Copy of cert to be forwarded
to me

b) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)

Inspected Y/N

Satisfactory Y/N

Notes:

No incidents
Good records of
Maintenance

e) STAFF COMPETENCE & TRAINING

No of Staff 10

No Questioned 1

Inspected Y/N

Satisfactory Y/N

Notes:

only Mr Scerabile takes
deliveries

c) VAPOUR RECOVERY CONNECTIONS & SIGNS

Inspected Y/N

Satisfactory Y/N

Notes:

Does the site have stage II vapour recovery? Y/N

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes:

Are procedures in place adequate in the event of any leaks or spillages? Y/N

Notes:

Inspector Chapman

Date 6th Sept 2010 11.45.

12.45

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.

Contract for the conduct of process permits: HDC & CCC