

**ENVIRONMENTAL PROTECTION
REPORT - VAPOUR RECOVERY**

APPENDIX 1

Premise SAINSBURY'S PETROL STATION Person Seen SEAN COLLINS
Address ST GERMAIN WALK. HUNTINGDON PE29 3FG

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS
AND ASSOCIATED LOG BOOK**

Inspected ☒ Y/N Satisfactory ☒ Y/N

Notes:

No leaks.

**d) TESTING CERTIFICATE FOR PRESSURE RELIEF
VALVES (Annual)**

Inspected ☒ Y/N Satisfactory ☒ Y/N

Notes:

TESTED 06/03/09

**b) LOG BOOK DETAILING MAINTENANCE,
EXAMINATION & TESTING, INVENTORY
CHECKING, INSTALLATION & REPAIR WORK
(SITE REGISTER)**

Inspected ☒ Y/N Satisfactory ☒ Y/N

Notes:

ALL OK.

e) STAFF COMPETENCE & TRAINING

No of Staff No Questioned

Inspected ☒ Y/N Satisfactory ☒ Y/N

Notes:

ALL OK.

**c) VAPOUR RECOVERY CONNECTIONS &
SIGNS**

Inspected ☒ Y/N Satisfactory ☒ Y/N

Notes:

ALL OK.

Does the site have stage II vapour recovery? ☒ Y/N

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory ☒ Y/N

Notes:

VERY GOOD.

Are procedures in place adequate in the event of any leaks or spillages? ☒ Y/N

Notes:

Inspector KIRSTY DRAYCOTT PETROLEUM
OFFICER CCC TRADING STANDARDS

Date 24/08/09

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.

Contract for the conduct of process permits: HDC & CCC