

**ENVIRONMENTAL PROTECTION  
REPORT - VAPOUR RECOVERY**

APPENDIX 1

Premise Burnsby's Petrol St.

Person Seen Heather Llewellyn

Address St Germain's Walks Huntingdon PE29 3FG

**OBSERVATIONS, ADVICE AND RECOMMENDATIONS:**

As a result of the inspection of your premises your attention is drawn to the following matters:

Routine inspection conducted on behalf of Huntingdon District Council

✓

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK**

Inspected Y/N

Satisfactory Y/N

Notes:

No incidents

✓

**d) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES (Annual)**

Inspected Y/N

Satisfactory Y/N

Notes:

E2S Pass  
Date of next test 11/03/12

✓

**b) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)**

Inspected Y/N

Satisfactory Y/N

Notes:

No log in site register - one to be made

**e) STAFF COMPETENCE & TRAINING**

No of Staff 10

No Questioned 1

Inspected Y/N

Satisfactory Y/N

Notes:

Heather does the training.

**c) VAPOUR RECOVERY CONNECTIONS & SIGNS**

Inspected Y/N

Satisfactory Y/N

Notes:

Does the site have stage II vapour recovery? Y/N

Notes:

**f) SITE MANAGEMENT & OTHER COMMENTS**

Satisfactory Y/N

Notes: weekly checks being conducted on pumps.

Are procedures in place adequate in the event of any leaks or spillages? Y/N

Notes:

Inspector

Miss H. R. Shepherd

Date

16/11/11

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.