

**ENVIRONMENTAL PROTECTION  
REPORT – VAPOUR RECOVERY**

APPENDIX 1

Premise Spaldwick Denim station Person Seen M R Karaman  
Address High st, Spaldwick PE2 8SD

**OBSERVATIONS, ADVICE AND RECOMMENDATIONS:**

As a result of the inspection of your premises your attention is drawn to the following matters:

VR signs required for tanks

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK**

Inspected Y/N Satisfactory Y/N

Notes: NO RECORDS OF ANY LEAKS

**d) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES (Annual)**

Inspected Y/N Satisfactory Y/N

Notes:

Gilbert & Keeler - root  
15 system inspected 14/02/10  
valid until 14/02/11

**b) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)**

Inspected Y/N Satisfactory Y/N

Notes: NO INFORMATION IN LOG BOOK  
CERTIFICATE IN LOG BOOK

**e) STAFF COMPETENCE & TRAINING**

No of Staff 1 No Questioned ☐

Inspected Y/N Satisfactory Y/N

Notes: 275 - MIN MAX READ

**c) VAPOUR RECOVERY CONNECTIONS & SIGNS**

Inspected Y/N Satisfactory Y/N

Notes: Y/N PIPES BUT NOT TANKS

Does the site have stage II vapour recovery? Y/N

Notes:

**f) SITE MANAGEMENT & OTHER COMMENTS**

Satisfactory Y/N

Notes:

RECORD KEEPING COULD BE BETTER

Are procedures in place adequate in the event of any leaks or spillages? Y/N

Notes:

Inspector Dan Burt Date 12/11/10

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation

hannah.shepherd@cambridgeshire.gov.uk

**ENVIRONMENTAL PROTECTION  
REPORT – VAPOUR RECOVERY**

APPENDIX 1

Premise Spaldwick service d Person Seen Mr Faraz  
Address High st Spaldwick PE28 0TD

**OBSERVATIONS, ADVICE AND RECOMMENDATIONS:**

As a result of the inspection of your premises your attention is drawn to the following matters:

Tanks labelled 5/3/11 premises brought into compliance

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS  
AND ASSOCIATED LOG BOOK**

Inspected Y/N Satisfactory Y/N

Notes:

/

**d) TESTING CERTIFICATE FOR PRESSURE RELIEF  
VALVES (Annual)**

Inspected Y/N Satisfactory Y/N

Notes:

/

**b) LOG BOOK DETAILING MAINTENANCE,  
EXAMINATION & TESTING, INVENTORY  
CHECKING, INSTALLATION & REPAIR WORK  
(SITE REGISTER)**

Inspected Y/N Satisfactory Y/N

Notes:

/

**e) STAFF COMPETENCE & TRAINING**

No of Staff ☐ No Questioned ☐

Inspected Y/N Satisfactory Y/N

Notes:

/

**c) VAPOUR RECOVERY CONNECTIONS &  
SIGNS**

Inspected Y/N Satisfactory Y/N

Notes:

/

Does the site have stage II vapour recovery? Y/N

Notes:

/

**f) SITE MANAGEMENT & OTHER COMMENTS**

Satisfactory Y/N

Notes:

/

Are procedures in place adequate in the event of any leaks or spillages? Y/N

Notes:

/

Inspector Chapman Date 14/03/11

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation