

**ENVIRONMENTAL PROTECTION
REPORT – VAPOUR RECOVERY**

APPENDIX 1

Premise Exco service st Person Seen MS L Pywell
Address St Marys Rd. Ramsey, Huntingdon PE26 2RD

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK

Inspected Y/N _____ Satisfactory Y/N _____

Notes:
No incidents

d) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES (Annual)

Inspected Y/N _____ Satisfactory Y/N _____

Notes:
Not seen

b) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)

Inspected Y/N _____ Satisfactory Y/N _____

Notes:
No incidents
Section in site register required

e) STAFF COMPETENCE & TRAINING

No of Staff ☒ No Questioned ☐

Inspected ☒ Satisfactory Y/N _____

Notes:
limited knowledge

c) VAPOUR RECOVERY CONNECTIONS & SIGNS

Inspected ☒ Satisfactory ☒ Y/N _____

Notes:

Does the site have stage II vapour recovery? ☒ Y/N _____

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N _____

Notes: Manager not present at time of inspection

Are procedures in place adequate in the event of any leaks or spillages? Y/N _____

Notes:

Inspector L. Deppa Date 03/09/10

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.

Contract for the conduct of process permits: HDC & CCC