

## Environmental permit inspection

**Name of permitted activity:** Sundown Bedding Products                      **Permit:** B02/06  
**Discussed with:** Simon    **Reference:** 105995  
**Inspector's Name:** Dave/ Aaron    **Date:** 21/05/2015

<b>Reason for visit:</b>	Follow up inspection from previous visit to discuss improvements.
<b>Issues discussed:</b>	Dust: Still clearing up excess dust from entire site. This is having
	the advantage of showing areas where plant has got leaks. Follow
	up work is including replacing damaged duct work with new, rather
	than patching up, and fixing obvious areas of escape e.g. silo.
	Cleaning and Maintenance schedules should be developed to
	ensure and show that progress is being made.
	Fire: Still considering that fire was caused by spark from main
	burner so employing a company that helped resolved fires in straw
	Process to investigate and resolve.
	Noise: wood dust silo unit has been replaced. Company is going to
	stop collecting whole pallets and purchase pre-shredded pallets
	This will reduce noise from removing shredding and reduce
number of nails entering system (which is causing damage to	
internal mechanisms.	
<b>Conditions breached:</b>	Not discussed any permit breaches.
<b>Risk assessment reevaluated :</b>	<b>NO</b>