

**ENVIRONMENTAL PROTECTION
REPORT – VAPOUR RECOVERY**

APPENDIX 1

Premise Bradway Garage Person Seen Ms Jackie Wilding
Address 289 Bradway, Yoxley Peterborough, PE7 3NR

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK

Inspected ☒ Y/N Satisfactory ☐ Y/N

Notes:

No incidents

d) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES (Annual)

Inspected ☒ Y/N Satisfactory ☒ Y/N ?

Notes:

Sept 07.
Further to a tel conversation with Mr Bass this is satisfactory.
(10/12/09 16:30)

b) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)

Inspected ☐ Y/N Satisfactory ☐ Y/N

Notes:

No incidents

e) STAFF COMPETENCE & TRAINING

No of Staff ☐ No Questioned ☐

Inspected ☐ Y/N Satisfactory ☐ Y/N

Notes:

Spoke to manager only 3 competent persons on site (assisted delivery)

c) VAPOUR RECOVERY CONNECTIONS & SIGNS

Inspected ☒ Y/N Satisfactory ☐ Y/N

Notes:

Due to high water levels unable to check all tank tops.

Does the site have stage II vapour recovery? ☒ Y/N

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory ☒ Y/N

Notes:

Are procedures in place adequate in the event of any leaks or spillages? Y/N

Notes:

Inspector Deborah Date 09/12/09 14.43

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.

Contract for the conduct of process permits: HDC & CCC

**ENVIRONMENTAL PROTECTION
REPORT – VAPOUR RECOVERY**

APPENDIX 1

Premise Broadway Garage Person Seen _____
Address 289 Broadway, Yaxley, Peterborough, PE7 3NR.

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

Letter sent re Vapour recovery test certificate (Sept 07)

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS
AND ASSOCIATED LOG BOOK**

Inspected Y/N _____ Satisfactory Y/N _____

Notes:

**d) TESTING CERTIFICATE FOR PRESSURE RELIEF
VALVES (Annual)**

Inspected Y/N _____ Satisfactory Y/N _____

Notes:

**b) LOG BOOK DETAILING MAINTENANCE,
EXAMINATION & TESTING, INVENTORY
CHECKING, INSTALLATION & REPAIR WORK
(SITE REGISTER)**

Inspected Y/N _____ Satisfactory Y/N _____

Notes:

e) STAFF COMPETENCE & TRAINING

No of Staff ☐ No Questioned ☐

Inspected Y/N _____ Satisfactory Y/N _____

Notes:

**c) VAPOUR RECOVERY CONNECTIONS &
SIGNS**

Inspected Y/N _____ Satisfactory Y/N _____

Notes:

Does the site have stage II vapour recovery? Y/N _____

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N _____

Notes:

Are procedures in place adequate in the event of any leaks
or spillages? Y/N _____

Notes:

Inspector: Heaphy

Date: 11/12/09

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.

Contract for the conduct of process permits: HDC & CCC