

ENVIRONMENTAL PROTECTION
REPORT – VAPOUR RECOVERY

APPENDIX 1

Premise Broadway Garage Person Seen Ms Caroline Morris
Address 289 Broadway Yorkley PE7 3NR

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

VR inspection required,

a) INCIDENTS OF VAPOUR LEAKS & LOCKS
AND ASSOCIATED LOG BOOK

Inspected Y/N

Satisfactory Y/N

Notes:

d) TESTING CERTIFICATE FOR PRESSURE RELIEF
VALVES (Annual)

Inspected Y/N

Satisfactory Y/N

Notes:

Expired

b) LOG BOOK DETAILING MAINTENANCE,
EXAMINATION & TESTING, INVENTORY
CHECKING, INSTALLATION & REPAIR WORK
(SITE REGISTER)

Inspected Y/N

Satisfactory Y/N

Notes:

No incidents

e) STAFF COMPETENCE & TRAINING

No of Staff ☐

No Questioned ☐

Inspected Y/N

Satisfactory Y/N

Notes:

c) VAPOUR RECOVERY CONNECTIONS &
SIGNS

Inspected Y/N

Satisfactory Y/N

Notes:

Does the site have stage II vapour recovery? Y/N

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes:

Are procedures in place adequate in the event of any leaks
or spillages? Y/N

Notes:

Inspector Alph Date 03/09/10

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.



**ENVIRONMENTAL PROTECTION
REPORT - VAPOUR RECOVERY**

Name Braedway Garage

Person Seen _____

Address 289 Braedway Garage, Yaxley, Peterborough PE7 3NR

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

Received copy of VR inspection - in date, premises
brought into compliance

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND
ASSOCIATED LOG BOOK**

Inspected Y/N

Satisfactory Y/N

Notes

/

**d) TESTING CERTIFICATE FOR PRESSURE RELIEF
VALVES (Annual)**

Inspected Y/N

Satisfactory Y/N

Notes

/

**b) LOG BOOK DETAILING MAINTENANCE,
EXAMINATION & TESTING, INVENTORY CHECKING,
INSTALLATION & REPAIR WORK (SITE REGISTER)**

Inspected Y/N

Satisfactory Y/N

Notes

/

e) STAFF COMPETENCE & TRAINING

No of Staff ☐

No Questioned ☐

Inspected Y/N

Satisfactory Y/N

Notes

/

c) VAPOUR RECOVERY CONNECTIONS & SIGNS

Inspected Y/N

Satisfactory Y/N

Notes

/

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes

/

Signed [Signature]

Tel / Email _____

Received by _____

Date/Time 18/02/11

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.

With Compliments

F.A.C. HAMMAN

SHEPHERD

Broadway Garage

BROADWAY

FPI. PRECISION TANK TESTING LTD
WHITE GATE FARM
DOWNHAM MARKET
NORFOLK PE38 0AY
TEL: 01366 388056

**PRECISION TANK TESTING LTD**

White Gate Farm
Downham West
Downham Market
Norfolk PE38 0AY
Tel/Fax: 01366 388056
Mobile: 07850 744140

VAPOUR RECOVERY TESTING STAGE 1B

This is to certify that on the date, as shown, our engineer attended the site as detailed below, and serviced the pressure vent valve/s and the vapour adaptor valve/s on the vapour recovery system Stage 1B.
The installation complied with the current regulations.

DATE OF CERTIFICATION24TH SEPTEMBER 2010**SITE:**

BROADWAY GARAGE

289 BROADWAY

YAXLEY

PETERBOROUGH PE7 3NR

NAME OF CERTIFYING**ENGINEER****SIGNATURE**

R. LONGMIR

THIS CERTIFICATE IS ONLY VALID IF IT IS AN ORIGINAL BEARING THE FPI STAMP
VAPOUR RECOVERY CERT.ML.2001