## ENVIRONMENTAL PROTECTION REPORT - VAPOUR RECOVERY

Premises hales Colon	Person Seen 6.8 Kuzikohoka
Address M. Nouth	
DESCRIPTIONS ADVICE AND DECOMMENDATIONS:	
OBSERVATIONS, ADVICE AND RECOMMENDATIONS:  As a result of the inspection of your premises your attention is drawn to the following matters:	
inspechen concluded both shopland tracing standards on behalf	
Works completed	
a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK	b) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES
Inspected Y/N Satisfactory Y/N	Inspected Y/N Satisfactory Y/N
Notes:	Notes: 17 110113
	Eds
c) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)	d) STAFF COMPETENCE & TRAINING No of Staff No Questioned
Inspected Y/N Satisfactory Y/N	Inspected Y/N Satisfactory Y/N
Notes: Notes:	Notes: Training records - a matrix duplo date.
e) VAPOUR RECOVERY CONNECTIONS & SIGNS	f) SITE MANAGEMENT & OTHER COMMENTS
Inspected Y/N Satisfactory Y/N	Satisfactory Y/N
Notes:	Notes: A well an oile
Two tento chechad due to	h wed min
vol'd tratha	
Does the site have stage II vapour recovery? Y/N	Are procedures in place adequate in the event of any leaks or spillages? Y/N
Notes:	Notes: Po Per RM
Signed 1111	Tel /Email <u>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</u>
Received by	Date/Time

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.