

**ENVIRONMENTAL PROTECTION
REPORT – VAPOUR RECOVERY**

Premises SAINSBURY'S PETROL STATION Person Seen HEATHER LIVERMORE
Address ST GERMAIN WALK, HUNTINGDON

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS
AND ASSOCIATED LOG BOOK**

Inspected Y/N Satisfactory Y/N

Notes: LOG COMPLETED
NO ISSUES RECORDED

**b) TESTING CERTIFICATE FOR PRESSURE RELIEF
VALVES**

Inspected Y/N Satisfactory Y/N

Notes: TEST CERTIFICATE 31/3/15

**c) LOG BOOK DETAILING MAINTENANCE,
EXAMINATION & TESTING, INVENTORY
CHECKING, INSTALLATION & REPAIR WORK
(SITE REGISTER)**

Inspected Y/N Satisfactory Y/N

Notes: RECORDS SATISFACTORY

d) STAFF COMPETENCE & TRAINING

No of Staff 9 No Questioned 1

Inspected Y/N Satisfactory Y/N

Notes: EXAMINED REFRESHER
TRAINING FORMS - GOOD

**e) VAPOUR RECOVERY CONNECTIONS &
SIGNS**

Inspected Y/N Satisfactory Y/N

Notes: ALL GOOD

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes: RECORDS SUFFICIENT
REFRESHER TRAINING
EVERY 6 MONTHS

Does the site have stage II vapour recovery? Y/N

Notes: RECORDS & CERTIFICATE
SEEN OKAY.

Are procedures in place adequate in the event of any leaks
or spillages? Y/N

Notes: PROCEDURES IN PLACE &
ALSO PART OF STAFF
TRAINING

Signed [Signature]

Tel /Email 01954 234 641

Received by M [Signature]

Date/Time 12/03/15 1130