

**ENVIRONMENTAL PROTECTION
REPORT - VAPOUR RECOVERY**

Premises Spaldwick Service Station Person Seen U T Durrant

Address High Street Spaldwick

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

inspection conducted on behalf of Huntingdon District Council.

a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK

Inspected Y/N

Satisfactory Y/N

Notes:

Nothing documented

b) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES

Inspected Y/N

Satisfactory Y/N

Notes:

c) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)

Inspected Y/N

Satisfactory Y/N

Notes:

Nothing documented
Tank 6 to Dev not documented.

d) STAFF COMPETENCE & TRAINING

No of Staff

7

No Questioned

1

Inspected Y/N

Satisfactory Y/N

Notes:

training records to be updated.
- In the near future theres going to be a change in staff.

e) VAPOUR RECOVERY CONNECTIONS & SIGNS

Inspected Y/N

Satisfactory Y/N

Notes:

Unable to hit tank tops
as tanker delivering

Does the site have stage II vapour recovery? Y/N

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes:

New manager
current manager leaving Friday.

Are procedures in place adequate in the event of any leaks or spillages? Y/N

Notes:

Signed [Signature]

Tel /Email 01454 284 628

Received by [Signature]

Date/Time 20/08/2013

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.

10/09/13 email received from area manager - confirming works done