ENVIRONMENTAL PROTECTION REPORT – VAPOUR RECOVERY

Premises SPALDWICK SS	Person Seeman
Address AIGH ST SPALDWIC	K. PEZ8 OTD.
Address 1414	· ·
OBSERVATIONS, ADVICE AND RECOMMENDATIONS: As a result of the inspection of your premises your attention is drawn to the following matters:	
As a result of the inspection of your premises your attention is drawn to the remaining many for the last to the second of the inspection of your premises your attention is drawn to the remaining many for the last to the second of the last to the	
FULL REBUILD.	
a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK	b) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES
Inspected Y/N Satisfactory Y/N	Inspected Y/N Satisfactory Y/N
Notes:	Notes: 15/7/2016
c) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)	d) STAFF COMPETENCE & TRAINING No of Staff No Questioned
Inspected Y/KI Satisfactory Y/KI	Inspected Y/N Satisfactory Y/N
Notes: SITE REGISTR IN PLACE	Notes: Fore Training 15/16.
e) VAPOUR RECOVERY CONNECTIONS & SIGNS	f) SITE MANAGEMENT & OTHER COMMENTS
Inspected Y/N Satisfactory Y/N	Satisfactory Y/N
Notes: Favor Bur Cigibile	Notes:
Does the site have stage II vapour recovery? Y/N	Are procedures in place adequate in the event of any leaks or spillages? Y/N
Notes:	Notes: The of TRAWING FOR COMP PURSON:
Signed	Tel/Email 01954 284621
Received by	Date/Time_\(\frac{11/1/2017}{}\)

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.