

ENVIRONMENTAL PROTECTION REPORT - VAPOUR RECOVERY

APPENDIX 1

Premise Brampton Nut connect

Person Seen _____

Address A14 Great North Road Brampton Kington PE28 4NQ

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

Routine inspection conducted on behalf of Kington District Council.

a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK

Inspected Y/N

Satisfactory Y/N

Notes:

NO incidents

d) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES (Annual)

Inspected Y/N

Satisfactory Y/N

Notes:

Stage 10 testing certificate of approval QS 17/02/11 passed

b) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)

Inspected Y/N

Satisfactory Y/N

Notes:

NO incidents

e) STAFF COMPETENCE & TRAINING

No of Staff 16

No Questioned 1

Inspected Y/N

Satisfactory Y/N

Notes:

c) VAPOUR RECOVERY CONNECTIONS & SIGNS

Inspected Y/N

Satisfactory Y/N

Notes:

to be cleaned -> reported during inspection

Does the site have stage II vapour recovery? Y/N

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes:

well run site

Are procedures in place adequate in the event of any leaks or spillages? Y/N

Notes:

Inspector

Chpmp

Miss H.R. Shepherd

Date

16/11/11

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.

18/01/12 Tel can confirmed all works completed.