

**ENVIRONMENTAL PROTECTION
REPORT – VAPOUR RECOVERY**

Premises BRAMPTON HUB CONNECT Person Seen LAURA
Address GREAT NORTH RD, BRAMPTON, HUNTINGDON, PE28 4NR

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

Inspection carried out on behalf of IDC

a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK

Inspected Y/N Satisfactory Y/N

Notes: PART OF SITE REGISTER - NO INCIDENTS RECORDED

b) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES

Inspected Y/N Satisfactory Y/N

Notes: TEST CERT 13/1/15

c) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)

Inspected Y/N Satisfactory Y/N

Notes: OK

d) STAFF COMPETENCE & TRAINING

No of Staff 16 No Questioned 1

Inspected Y/N Satisfactory Y/N

Notes: ONLINE TRAINING RECORDS. WEEKLY SAFETY CHECKS.

e) VAPOUR RECOVERY CONNECTIONS & SIGNS

Inspected Y/N Satisfactory Y/N

Notes: VIR SIGNS NEED CLEANING IN TANKS

Does the site have stage II vapour recovery? Y/N

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes: GOOD.

Are procedures in place adequate in the event of any leaks or spillages? Y/N

Notes: STAFF TRAINING & WEEKLY SAFETY CHECKS

Signed [Signature]

Tel /Email 01954 284 641

Received by [Signature]

Date/Time 7/1/15

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.