ENVIRONMENTAL PROTECTION REPORT – VAPOUR RECOVERY

APPENDIX 1

Premise Teaco Service Station	Person Seen
Address Texosteres Itu 156	S Riplan reed, Kenhugalan, PE282
OBSERVATIONS, ADVICE AND RECOMME As a result of the inspection of your premises your	
*	
a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK	d) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES (Annual)
Inspected Y/N Satisfactory Y/N	Inspected YNN Satisfactory YN
Notes:	Notes:
b) LOG BOOK DETAILING MAINTENANCE,	e) STAFF COMPETENCE & TRAINING No of Staff No Questioned
EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)	
Inspected Y/N Satisfactory Y/N	Inspected Y/N Satisfactory Y/N
Notes:	Notes:
Noircidants	Spelve to Menagera DCD box a Some URINFO in training
c) VAPOUR RECOVERY CONNECTIONS &	f) SITE MANAGEMENT & OTHER COMMENTS
ŚIGNS	Satisfactory Y/N
Inspected Y/N Satisfactory Y/N Notes: Washe to see due to Wigh Zenter Levels	Notes:
Does the site have stage II vapour recovery? Y/N Notes:	Are procedures in place adequate in the event of any leaks or spillages? Y/N Notes:
(Mashal)	Des Mala Calla

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.

Contract for the conduct of process permits: HDC & CCC