

**ENVIRONMENTAL PROTECTION
REPORT – VAPOUR RECOVERY**

Premises TESCO SERVICE STATION Person Seen _____
Address BARFORD RD, EYNEBURY, ST NEOTS PE19 2SA

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS
AND ASSOCIATED LOG BOOK**

Inspected Y/N Satisfactory Y/N

Notes: WEEKLY TESTING
OF SYSTEMS - RECORDED

**b) TESTING CERTIFICATE FOR PRESSURE RELIEF
VALVES**

Inspected Y/N Satisfactory Y/N

Notes:

**c) LOG BOOK DETAILING MAINTENANCE,
EXAMINATION & TESTING, INVENTORY
CHECKING, INSTALLATION & REPAIR WORK
(SITE REGISTER)**

Inspected Y/N Satisfactory Y/N

Notes:

d) STAFF COMPETENCE & TRAINING

No of Staff

11

No Questioned

1

Inspected Y/N

Satisfactory Y/N

Notes: ALL TRAINING DOCUMENTED

**e) VAPOUR RECOVERY CONNECTIONS &
SIGNS**

Inspected Y/N Satisfactory Y/N

Notes: SIGN STARTING TO
FADE FOR "NO SMOKING"
- ADVISED

Does the site have stage II vapour recovery? Y/N

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes: RECORDS KEPT UP TO DATE

Are procedures in place adequate in the event of any leaks
or spillages? Y/N

Notes: COVERED IN STAFF TRAINING

Signed [Signature]

Tel /Email 01954 284 641

Received by [Signature]

Date/Time 8/9/15