

**ENVIRONMENTAL PROTECTION**  
**REPORT – VAPOUR RECOVERY**

Premises SHIELL HUNTINGDON

Person Seen PRABAKARAN  
THEYNGARASA

Address STUKELY ROAD, HUNTINGDON, PE29 6HG

**OBSERVATIONS, ADVICE AND RECOMMENDATIONS:**

As a result of the inspection of your premises your attention is drawn to the following matters:

Inspection conducted on behalf of the District Council.

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK**

Inspected Y/N Satisfactory Y/N

Notes:

No incidents recorded

**b) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES**

Inspected ☒ Y/N Satisfactory ☒ Y/N

Notes:

Certificate dated until 23/04/18  
TOXHEIM  
E+S expired 30/11/18 S1 + S2.

**c) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)**

Inspected Y/N Satisfactory Y/N

Notes:

No log book

**d) STAFF COMPETENCE & TRAINING**

No of Staff ☒ 6 No Questioned ☐

Inspected Y/N

Satisfactory Y/N

Notes:

MANAGER NOT ON TRAINING LOG.

**e) VAPOUR RECOVERY CONNECTIONS & SIGNS**

Inspected Y/N Satisfactory Y/N

Notes:

Tank tops lifted - all  
satisfactory.

Does the site have stage II vapour recovery? ☒ Y/N

Notes:

**f) SITE MANAGEMENT & OTHER COMMENTS**

Satisfactory Y/N

Notes:

Limited understanding of site,  
not all documentation available  
Please see rectification advice

Are procedures in place adequate in the event of any leaks or spillages? Y/N

Notes:

P.A not seen

Signed [Signature]

Tel /Email 01954 284628

Received by [Signature]

Date/Time 4/3/2017

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.