

**ENVIRONMENTAL PROTECTION
REPORT - VAPOUR RECOVERY**

APPENDIX 1

Premise SW Highland Person Seen Mr Highland
Address Bluntham Service St, Station Road, Bluntham PE28 3PA

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:
As a result of the inspection of your premises your attention is drawn to the following matters:
VIR inspection / test cert required every three year. No installation & testing Dec 09.

a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK
Inspected Y/N _____ Satisfactory Y/N _____
Notes:
No incidents

d) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES (Annual)
Inspected Y/N _____ Satisfactory Y/N _____
Notes:

b) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)
Inspected Y/N _____ Satisfactory Y/N _____
Notes:
No incidents

e) STAFF COMPETENCE & TRAINING
No of Staff No Questioned 1
Inspected Y/N _____ Satisfactory Y/N _____
Notes:
All staff that are competent have been working on the site for number of years

c) VAPOUR RECOVERY CONNECTIONS & SIGNS
Inspected Y/N _____ Satisfactory Y/N _____
Notes:
Vents 1 & 4 to be checked
Does the site have stage II vapour recovery? Y/N
Notes:

f) SITE MANAGEMENT & OTHER COMMENTS
Satisfactory Y/N _____
Notes:
well run site
Are procedures in place adequate in the event of any leaks or spillages? Y/N
Notes:

Inspector Chapman Date 18th Oct 09

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation