APPENDIX 1

ENVIRONMENTAL PROTECTION REPORT - VAPOUR RECOVERY

Premise RAINBOW BY SCHUICE STATION Person Seen TOM DAWSON	
Address NEWTOWN 10AD: PAMSEY	
OBSERVATIONS, ADVICE AND RECOMMENDATIONS: As a result of the inspection of your premises your attention is drawn to the following matters:	
a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK Inspected YIN Satisfactory YIN Notes:	d) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES (Annual) Inspected YIN Satisfactory (YIN Notes:
NO INCIDENTS	TESTED 31/03/09
b) LOG BOOK DETAILING, MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER) Inspected YN Satisfactory (N) Notes:	e) STAFF COMPETENCE & TRAINING No of Staff No Questioned 3 Inspected N Satisfactory N Notes:
c) VAPOUR RECOVERY CONNECTIONS & SIGNS	1) SITE MANAGEMENT & OTHER COMMENTS
Inspected YIN Satisfactory (YIN Notes:	Notes:
Does the site have stage il vapour recovery? Y(N) Notes:	Are procedures in place adequate in the event of any leaks or splitages? YN Notes:
Inspector KIRSTY DRAY(OTT CCC TRADING STANDARDS	Date 09 10 09

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.