and the second s	The second secon
ENVIRONMENTAL REPORT – VAPOL	
- Parta Devas	Person Seen W (Garden
Premise Range Device of Person Seen Address Merkan rad Range P(26165)	
Address_/v Class, / v	
OBSERVATIONS, ADVICE AND RECOMMENDATIONS: As a result of the inspection of your premises your attention is drawn to the following matters:	
a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK	d) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES (Annual)
Inspected Y/N Satisfactory Y/N	Inspected Y/N Satisfactory (7/N Notes: Hole J 19 104 11
Notes:	22/05/10/0
Nowuceits	Exemple 22/05/11
b) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY	e) STAFF COMPETENCE & TRAINING No of Staff No Questioned
CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)	Inspected Y/N Satisfactory Y/N
Inspected (IX) Satisfactory (IX)	N.A.
Notes:	Levited browledge DCD site
1000000	Den site
	DCD M
c) VAPOUR RECOVERY CONNECTIONS &	f) SITE MANAGEMENT & OTHER COMMENTS
SIGNS Inspected VIN Satisfactory Y/N	Satisfactory Y/N
Inspected V(N) Satisfactory Y/N Notes: 7CMKS 12 3 16 hcmg	Hopesining needs addressing
URsign	Are procedures in place adequate in the event of any leaks
Does the site have stage II vapour recovery? Y/N	or spillages? Y/N Notes:
Notes:	10000
Markon	20/01/12
Inspector	Date

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.

Contract for the conduct of process permits: HDC & CCC