

**ENVIRONMENTAL PROTECTION  
REPORT – VAPOUR RECOVERY**

Premises Romney Co-operative Newst Person Seen M, M Hales  
Address Newton Rd Romney PE26 1CJ

**OBSERVATIONS, ADVICE AND RECOMMENDATIONS:**

As a result of the inspection of your premises your attention is drawn to the following matters:

Inspection conducted on behalf of Wenhaydon District Council.

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS  
AND ASSOCIATED LOG BOOK**

Inspected Y/N Satisfactory Y/N

Notes:

No incidents recorded

**b) TESTING CERTIFICATE FOR PRESSURE RELIEF  
VALVES**

Inspected Y/N Satisfactory Y/N

Notes:

30/4/2016 Ed D  
- Pass.

**c) LOG BOOK DETAILING MAINTENANCE,  
EXAMINATION & TESTING, INVENTORY  
CHECKING, INSTALLATION & REPAIR WORK  
(SITE REGISTER)**

Inspected Y/N Satisfactory Y/N

Notes:

No incidents recorded

**d) STAFF COMPETENCE & TRAINING**

No of Staff 6 No Questioned 1

Inspected Y/N

Satisfactory Y/N

Notes:

Driver controlled

**e) VAPOUR RECOVERY CONNECTIONS &  
SIGNS**

Inspected Y/N Satisfactory Y/N

Notes:

Does the site have stage II vapour recovery? Y/N

Notes:

**f) SITE MANAGEMENT & OTHER COMMENTS**

Satisfactory Y/N

Notes:

Are procedures in place adequate in the event of any leaks  
or spillages? Y/N

Notes:

Risk assessment

Signed [Signature]

Tel /Email 01954 284628

Received by [Signature]

Date/Time 4 May 2016

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.