

**ENVIRONMENTAL PROTECTION
REPORT – VAPOUR RECOVERY**

APPENDIX 1

Premise Pace Redwings Person Seen Mr Bharat Prasad
Address Old Great North Road, Schwry, Kunkhigden, PE28 5XP

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

Inspection conducted on behalf of Kunkhigden District Council.
26/10/11 Tel can stating works done

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS
AND ASSOCIATED LOG BOOK**

Inspected Y/N Satisfactory Y/N

Notes:

No incidents

**d) TESTING CERTIFICATE FOR PRESSURE RELIEF
VALVES (Annual)**

Inspected Y/N Satisfactory Y/N

Notes:

Not available

**b) LOG BOOK DETAILING MAINTENANCE,
EXAMINATION & TESTING, INVENTORY
CHECKING, INSTALLATION & REPAIR WORK
(SITE REGISTER)**

Inspected Y/N Satisfactory Y/N

Notes:

No incidents

e) STAFF COMPETENCE & TRAINING

No of Staff ☐ No Questioned ☐

Inspected Y/N Satisfactory Y/N

Notes:

competent persons register
to be updated

**c) VAPOUR RECOVERY CONNECTIONS &
SIGNS**

Inspected Y/N Satisfactory Y/N

Notes:

Does the site have stage II vapour recovery? Y/N

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes:

small site

Are procedures in place adequate in the event of any leaks
or spillages? Y/N

Notes:

old site. sure site compliance

Inspector [Signature] Date 07/10/11

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.