

**ENVIRONMENTAL PROTECTION
REPORT – VAPOUR RECOVERY**

Premises Redwings Person Seen Mr Tony Marsh
Address Great North Road Luton

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

inspection conducted on behalf of Luton District Council

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS
AND ASSOCIATED LOG BOOK**

Inspected Y/N Satisfactory Y/N

Notes:

No incidents

**b) TESTING CERTIFICATE FOR PRESSURE RELIEF
VALVES**

Inspected Y/N Satisfactory Y/N

Notes:

9/3/12

**c) LOG BOOK DETAILING MAINTENANCE,
EXAMINATION & TESTING, INVENTORY
CHECKING, INSTALLATION & REPAIR WORK
(SITE REGISTER)**

Inspected Y/N Satisfactory Y/N

Notes:

No incidents
Nothing documented - TO BE

d) STAFF COMPETENCE & TRAINING

No of Staff

3

No Questioned

1

Inspected Y/N

Satisfactory Y/N

Notes:

staff training to be evidenced

**e) VAPOUR RECOVERY CONNECTIONS &
SIGNS**

Inspected Y/N Satisfactory Y/N

Notes:

Unit 4 requires
VR sign.

Does the site have stage II vapour recovery? Y/N

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes:

if you can't locate staff
training material please email
me and I will forward you some

Are procedures in place adequate in the event of any leaks
or spillages? Y/N

Notes:

Signed

[Signature]

Tel /Email

hannah.shepherd@cambridgeshire.gov.uk

Received by

[Signature]

Date/Time

10/02/14 9.40

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.