

**ENVIRONMENTAL PROTECTION  
REPORT – VAPOUR RECOVERY**

APPENDIX 1

Premise Shell Tenstenton Person Seen Mr Z. Gibbie  
Address Cambridge road, Tenstenton, Nunhadden, PE28 9HY

**OBSERVATIONS, ADVICE AND RECOMMENDATIONS:**

As a result of the inspection of your premises your attention is drawn to the following matters:

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS  
AND ASSOCIATED LOG BOOK**

Inspected Y/N

Satisfactory Y/N

Notes:

**d) TESTING CERTIFICATE FOR PRESSURE RELIEF  
VALVES (Annual)**

Inspected Y/N

Satisfactory Y/N

Notes:

~~expired 15/05/10~~  
07/10/10

**b) LOG BOOK DETAILING MAINTENANCE,  
EXAMINATION & TESTING, INVENTORY  
CHECKING, INSTALLATION & REPAIR WORK  
(SITE REGISTER)**

Inspected Y/N

Satisfactory Y/N

Notes:

**e) STAFF COMPETENCE & TRAINING**

No of Staff ☐

No Questioned ☐

Inspected Y/N

Satisfactory Y/N

Notes:

7 people do deliveries does  
8 people work on site

**c) VAPOUR RECOVERY CONNECTIONS &  
SIGNS**

Inspected Y/N

Satisfactory Y/N

Notes:

High levels of water in  
tanks unable to recall risks

Does the site have stage II vapour recovery? Y/N

Notes:

**f) SITE MANAGEMENT & OTHER COMMENTS**

Satisfactory Y/N

Notes:

limited knowledge on  
vapour recovery.

Are procedures in place adequate in the event of any leaks  
or spillages? Y/N

Notes:

Inspector

Deputy H.P. Shepherd

Date

27/01/11

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation