## ENVIRONMENTAL PROTECTION REPORT - VAPOUR RECOVERY

Premises SHELL FONSTATION	Person Seen Monamo.
Address A14 FONSTANTON C	AMES.
Addiooo_	
OBSERVATIONS, ADVICE AND RECOMMENDATIONS:	
As a result of the inspection of your premises your attention is drawn to the following matters:	
NONE	
	b) TESTING CERTIFICATE FOR PRESSURE RELIEF
a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK	VALVES
Inspected Y/N Satisfactory Y/N	Inspected Y/N Satisfactory Y/N
Notes:  ONASSISTED DELIVERED  STAFF WONE NOTICE	Notes: NAT 15 STACE 1+2
c) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)	d) STAFF COMPETENCE & TRAINING No of Staff No Questioned
Inspected Y/M Satisfactory Y/M	Inspected Y/N Satisfactory Y/N
Notes:	Notes:  ON LINE TRAINING  SHELL STANDARD FORMIT
e) VAPOUR RECOVERY CONNECTIONS & SIGNS	f) SITE MANAGEMENT & OTHER COMMENTS
Inspected Y/M Satisfactory Y/M	Satisfactory Y/N
Notes:  IN PARCE + LIGIBLE  ALL LOCKED + STEURE.	Notes:
Does the site have stage II vapour recovery? Y/M-	Are procedures in place adequate in the event of any leaks or spillages? Y/N
Notes: Plalage	Notes:
Signed	alan. easey @ combandsestive.gov. UK  Tel/Email 01954 284621
Received by Dogel	Date/Time 9/3/2017

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.