

**ENVIRONMENTAL PROTECTION
REPORT - VAPOUR RECOVERY**

128569vr

Premises SHELL Person Seen AJUD
Address LAMSEY RD ST IVEY OXON.

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS
AND ASSOCIATED LOG BOOK**

Inspected Y/N

Satisfactory Y/N

Notes:

SITE REGISTER

**b) TESTING CERTIFICATE FOR PRESSURE RELIEF
VALVES**

Inspected Y/N

Satisfactory Y/N

Notes:

DUE AUG 2014

**c) LOG BOOK DETAILING MAINTENANCE,
EXAMINATION & TESTING, INVENTORY
CHECKING, INSTALLATION & REPAIR WORK
(SITE REGISTER)**

Inspected Y/N

Satisfactory Y/N

Notes:

d) STAFF COMPETENCE & TRAINING

No of Staff 4

No Questioned 2

Inspected Y/N

Satisfactory Y/N

Notes:

**e) VAPOUR RECOVERY CONNECTIONS &
SIGNS**

Inspected Y/N

Satisfactory Y/N

Notes:

REQUIRE CLEANING
NOT LOGABLE

Does the site have stage II vapour recovery? Y/N N

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes:

3RD PARTY ASSESSMENT OF STOCK
RECONCILIATION BY TANKAGE
NO REFERENCES FOR LAST 6
MONTHS.

Are procedures in place adequate in the event of any leaks
or spillages? Y/N

Notes:

2 PORTAL SHELL TRAININGS

Signed AJUD

Tel /Email alan. eason@oxfordshire.gov.uk

Received by AJUD

Date/Time 7/7/2014

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.

**ENVIRONMENTAL PROTECTION
REPORT - VAPOUR RECOVERY**

Premises Shaw Ramsey Rd. Person Seen James
Address Braley Road, St Ives, Cambs.

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS
AND ASSOCIATED LOG BOOK**

Inspected Y/N

Satisfactory Y/N

Notes:

Site Register

**b) TESTING CERTIFICATE FOR PRESSURE RELIEF
VALVES**

Inspected Y/N

Satisfactory Y/N

Notes:

11/8/2014 E+S Certificate

**c) LOG BOOK DETAILING MAINTENANCE,
EXAMINATION & TESTING, INVENTORY
CHECKING, INSTALLATION & REPAIR WORK
(SITE REGISTER)**

Inspected Y/N

Satisfactory Y/N

Notes:

As Above

d) STAFF COMPETENCE & TRAINING

No of Staff

7

No Questioned

1

Inspected Y/N

Satisfactory Y/N

Notes:

**e) VAPOUR RECOVERY CONNECTIONS &
SIGNS**

Inspected Y/N

Satisfactory Y/N

Notes:

VR Signs Sign on connection
missing
(could be undertaken)

Does the site have stage II vapour recovery? Y/N

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes:

Standard Site Procedures

Are procedures in place adequate in the event of any leaks
or spillages? Y/N

Notes:

ON CALL SERVICE + IN HOUSE
TRAINING.

Signed

[Signature]

Tel /Email

01954 284621

alan.perry@cambridgeshire.gov.uk

Received by

[Signature]

Date/Time

30/3/2015

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.