



REPORT - VAPOUR RECOVERY

Name Malthurst Kensington

Person Seen Norshade

Address Kensington Norton Bypass, North Road, PE28 2DN

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK

Inspected Y/N

Satisfactory Y/N

Notes No incidents recorded.

d) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES (Annual)

Inspected Y/N

Satisfactory Y/N

Notes certificate not in file register - caps to be forwarded to site 06/10/10

b) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)

Inspected Y/N

Satisfactory Y/N

Notes No record of incidents / Pauline recorded.

e) STAFF COMPETENCE & TRAINING

No of Staff ☒

No Questioned ☐



Inspected Y/N

Satisfactory Y/N

Notes

c) VAPOUR RECOVERY CONNECTIONS & SIGNS

Inspected Y/N

Satisfactory Y/N

Notes unable to lift tank tops adv given

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes

Signed

Deputy HANNAH STEPHENSON

Tel / Email

0154 284 628

Received by

Date/Time

27/01/11

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.