

**ENVIRONMENTAL PROTECTION
REPORT – VAPOUR RECOVERY**

Premises Nat Hurst Kennington

Person Seen Mr Joseph (Manager)

Address Marsh Road, Herford Kennington

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

Inspection conducted on behalf of District Council

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS
AND ASSOCIATED LOG BOOK**

Inspected Y/N

Satisfactory Y/N

Notes:

Nothing documented

**b) TESTING CERTIFICATE FOR PRESSURE RELIEF
VALVES**

Inspected Y/N

Satisfactory Y/N

Notes:

3/11/16

**c) LOG BOOK DETAILING MAINTENANCE,
EXAMINATION & TESTING, INVENTORY
CHECKING, INSTALLATION & REPAIR WORK
(SITE REGISTER)**

Inspected Y/N

Satisfactory Y/N

Notes:

Nothing documented

d) STAFF COMPETENCE & TRAINING

No of Staff

3

No Questioned

☐

certificate on training CD

Inspected Y/N

Satisfactory Y/N

Notes:

**e) VAPOUR RECOVERY CONNECTIONS &
SIGNS**

Inspected Y/N

Satisfactory Y/N

Notes:

Heavy tank tops
inspected T4 BOW
all satisfactory

Does the site have stage II vapour recovery? Y/N

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes:

Appears to be a well run site

Are procedures in place adequate in the event of any leaks
or spillages? Y/N

Notes:

Risk assessed

Signed

[Signature]

Tel /Email

01954 284 628

Received by

J.M.F.

Date/Time

16/6/16

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.