

ENVIRONMENTAL PROTECTION
REPORT - VAPOUR RECOVERY

Premises Alconbury Service Station Person Seen Ms M Lambert
Address Rush Lane Alconbury Huntingdon PE28 1DS

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

Vapour recovery inspection conducted on behalf of Huntingdon District Council

a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK

Inspected Y/N ☒ Satisfactory Y/N ☒

Notes:

b) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES

Inspected Y/N ☒ Satisfactory Y/N ☒

Notes:

100% tanks serviced V.R 10/12/15
~ V.R cap inoperative required replacing.
~ V.R pressure test undertaken?

c) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)

Inspected Y/N ☒ Satisfactory Y/N ☒

Notes:

Tank 5 switch to vapour recovery changed 2014.
11/12/15 defective V.R cap changed

d) STAFF COMPETENCE & TRAINING

No of Staff ☒ 4 No Questioned ☒ 1

Inspected Y/N ☒

Satisfactory Y/N ☒

Notes:

only one competent person. Training arranged for the near future.

e) VAPOUR RECOVERY CONNECTIONS & SIGNS

Inspected Y/N ☒ Satisfactory Y/N ☒

Notes:

Does the site have stage II vapour recovery? ☒ Y/N

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N ☒

Notes:

DSCAR risk assessment to be completed

Are procedures in place adequate in the event of any leaks or spillages? ☒ Y/N

Notes:

None

Signed [Signature]

Tel / Email 01954 284 628

Received by M Lambert

Date/Time 4 May 2016

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.