

**ENVIRONMENTAL PROTECTION  
REPORT - VAPOUR RECOVERY**

13/942

Premises LITTLEHAMPTON SS Person Seen STEFAN  
Address LONDON ROAD, YAXLEY, CAMBS

**OBSERVATIONS, ADVICE AND RECOMMENDATIONS:**

As a result of the inspection of your premises your attention is drawn to the following matters:

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS  
AND ASSOCIATED LOG BOOK**

Inspected Y/~~N~~ Satisfactory Y/~~N~~

Notes:

REGISTER NOW COVERED  
BY SURSITE

**b) TESTING CERTIFICATE FOR PRESSURE RELIEF  
VALVES**

Inspected Y/~~N~~ Satisfactory Y/~~N~~

Notes:

FEB 2017 DUE AT TIME  
OF VISIT.

**c) LOG BOOK DETAILING MAINTENANCE,  
EXAMINATION & TESTING, INVENTORY  
CHECKING, INSTALLATION & REPAIR WORK  
(SITE REGISTER)**

Inspected Y/~~N~~ Satisfactory Y/~~N~~

Notes:

SITE REGISTER.

**d) STAFF COMPETENCE & TRAINING**

No of Staff 7 No Questioned 1

Inspected Y/~~N~~ Satisfactory Y/~~N~~

Notes:

MOST DEFECTS SEEN IN

**e) VAPOUR RECOVERY CONNECTIONS &  
SIGNS**

Inspected Y/~~N~~ Satisfactory Y/~~N~~

Notes:

CONNECTIONS OK.  
SIGN FADED ON LEFT  
SIDE CONNECTION.

Does the site have stage II vapour recovery? ~~Y~~/N

Notes:

**f) SITE MANAGEMENT & OTHER COMMENTS**

Satisfactory Y/~~N~~

Notes:

WATER RUN.

Are procedures in place adequate in the event of any leaks  
or spillages? Y/~~N~~

Notes:

Signed 

Tel /Email alan.eassey@cambridgehire.gov.uk

Received by X

Date/Time 8/2/2017

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.