

**ENVIRONMENTAL PROTECTION
REPORT - VAPOUR RECOVERY**

APPENDIX 1

Premise Longsore Garage

Person Seen Mr Scarafile

Address St Neots PE19 1JZ

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

Documents - as at 16/11/12

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS
AND ASSOCIATED LOG BOOK**

Inspected Y/N

Satisfactory Y/N

Notes:

No incidents

**d) TESTING CERTIFICATE FOR PRESSURE RELIEF
VALVES (Annual)**

Inspected Y/N

Satisfactory Y/N

Notes:

**b) LOG BOOK DETAILING MAINTENANCE,
EXAMINATION & TESTING, INVENTORY
CHECKING, INSTALLATION & REPAIR WORK
(SITE REGISTER)**

Inspected Y/N

Satisfactory Y/N

Notes:

e) STAFF COMPETENCE & TRAINING

No of Staff 10

No Questioned ☐

Inspected Y/N

Satisfactory Y/N

Notes:

**c) VAPOUR RECOVERY CONNECTIONS &
SIGNS**

Inspected Y/N

Satisfactory Y/N

Notes:

Does the site have stage II vapour recovery? Y/N

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes:

Are procedures in place adequate in the event of any leaks
or spillages? Y/N

Notes:

Inspector Chapman

Date 18/11/12

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.

Contract for the conduct of process permits: HDC & CCC