## **Risk Assessment for Local Air Pollution Control**

Name of permitted activity:	Eaton Tractors Ltd	PG	Note:	PG3/1	6	
Discussed with:	Vince	LA Refe	rence:	B13/9	3	
Inspector's Name:	Dave Bass		Date:	09/03/	2010	
Operator Performance Ar	nnraical		_			
Operator Performance Ap						
Scale of Non-Compliance		Possi	Possible Scores		Scores Awarded	
(A) Incident leading to justified complaint but no breach of specific permit condition or of general/residual BAT condition		0 points				
(B) Incident leading to a justified com	plaint <sup>*</sup>	5 per incident				
(C) Breach of permit not leading to fo	rmal action	10 pe	10 per incident			
(D) Incident leading to formal caution	, Enforcement Notice or prosecution	15 per incident				
(E) Incident leading to a Prohibition Notice		20 per incident				
Total		(Max. 50		ax. 50)		
* Unjustified complaints may be e.g. t linked to an incident at the process.	hose considered by the inspector to be unrea	asonable c	or which ca	annot be	clearly	
Where facility has been on Reduce	d Charge due to Mothballing or Reduced	Operating	Levels			
<ul><li>(f) Failure to notify the regulator or re- above the threshold requiring a permaceptance letter</li></ul>	ure to notify the regulator or restart or increase in level of operation to the threshold requiring a permit at the installation in accordance with the ance letter					
Total (applies only when condition		(Max 75)				
Scoring for Component 2 - Assess	ment of Monitoring, Maintenance and Rec	ords			_	
Criterion	Criterion		Possible Scores		Scores	
		Yes	No	N/A	Awarded	
<ul><li>(A) Are emissions monitored as requi Are emissions and emissions monitor</li></ul>	red in the permit? ring recorded as required in the permit?	0	<del>10</del>	0	0	
(B) Monitoring requirements reduced compliance?	because results over time show consistent	0	0	0	0	
(C) Is an appropriate maintenance sc	hedule in place and available on request?	0	5	0	0	
(D) Fully documented and adhered permit?	to maintenance programme, in line with	0	5	0	5	
(E) Full documented records as requi	red in permit available on-site?	0	5	0	0	
(F) Has the operator notified the regu	lator promptly of all relocations of all plant?	<del>-5</del>	<del>10</del>	0	0	
Total score			(-5 to 35)		5	
	·				•	

Component 3 - Assessment of Management, Training and Responsibility					
Criterian	Possible Scores			Scores	
Criterion		No	N/A	Awarded	
(A) Are procedures in place to ensure proper management, supervision and training for process operations, proper use of equipment and effective preventative maintenance on all plant and equipment concerned with the control of emissions to air?	0	<del>5</del>	0	0	
(B) Specific responsibilities assigned to individual staff for these procedures?	0	5	0	0	
(C) Does the operator maintain, and make available on request, a statement of training requirements for each operational post?	0	5	0	0	
(D) Are all staff with responsibility for operating the process sufficiently trained to be aware of their responsibilities under the permit, minimising emissions on start up and shut down and taking action to minimise emissions during abnormal conditions?	0	5	0	0	
(E) Trained staff on site throughout periods where potentially air-polluting activities take place?	0	5	0	0	
(F) Is an 'appropriate' environmental management system in place?	<del>-5</del>	0	0	0	
Total	(-5 to 25) <b>0</b>		0		
Total Score for Operator Performance Appraisal	Range -10 to 110 (135)		0		

Overall scores	Score given
Operator Performance Appraisal	
Compliance Assessment	0
Assessment of Monitoring, Maintenance and Records	5
Assessment of Management, Training and Responsibility	0
Total score	5

OVERALL SCORE FOR THE PROCESS	Range -10 to 110 (135)	5
REGULATORY EFFORT CATEGORY		
* high=score of >55, medium 30-55 and low <30	LOW, MED, HIGH	LOW

## Comments

Crusher only been used 6 times in last year. Possibly falls within T7 exemption so gave criteria to and advised them to apply if they think they do. Only one operator for the crusher who knows how use the machine but no evidence of any formal/informal training but aware of responsibilities to keeping dust levels down. No record seen for maintenance of machine.