

**ENVIRONMENTAL PROTECTION  
REPORT – VAPOUR RECOVERY**

APPENDIX 1

Premise Shell Kingdon Person Seen Mr Adner Juel  
Address Stokeley road Kinghydon PE29 6HG

**OBSERVATIONS, ADVICE AND RECOMMENDATIONS:**

As a result of the inspection of your premises your attention is drawn to the following matters:

Conducted on behalf of Kinghydon District Council

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS  
AND ASSOCIATED LOG BOOK**

Inspected Y/N Satisfactory Y/N

Notes:

No incidents

**d) TESTING CERTIFICATE FOR PRESSURE RELIEF  
VALVES (Annual)**

Inspected ☒ Y/N Satisfactory Y/N

Notes:

Eas dated test 17/11/11  
Date of next test 17/11/14

**b) LOG BOOK DETAILING MAINTENANCE,  
EXAMINATION & TESTING, INVENTORY  
CHECKING, INSTALLATION & REPAIR WORK  
(SITE REGISTER)**

Inspected Y/N Satisfactory Y/N

Notes:

No incidents

**e) STAFF COMPETENCE & TRAINING**

No of Staff  No Questioned

Inspected ☒ Y/N Satisfactory Y/N

Notes:

Notes on VR on wall  
unassisted deliveries

**c) VAPOUR RECOVERY CONNECTIONS &  
SIGNS**

Inspected Y/N Satisfactory Y/N

Notes:

due to works being conducted  
on site need cleaning

Does the site have stage II vapour recovery? ☒ Y/N

Notes:

—

**f) SITE MANAGEMENT & OTHER COMMENTS**

Satisfactory Y/N

Notes:

Are procedures in place adequate in the event of any leaks  
or spillages? Y/N

Notes:

DSAR Risk assessment to be  
updated

Inspector M. R. Shepherd

Cambridgeshire County Council  
Trading Standards

Date 24/11/11

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legisla

02/12/11 reconnection advice received all works  
completed