

**ENVIRONMENTAL PROTECTION
REPORT - VAPOUR RECOVERY**

APPENDIX 1

Premise Kings Lane Garage Person Seen Vic Scarafic
 Address Kings Lane, St Neots, PE19 1JZ

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:
 As a result of the inspection of your premises your attention is drawn to the following matters:

a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK

Inspected Y/N Satisfactory Y/N

Notes: All OK.

d) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES (Annual)

Inspected Y/N Satisfactory Y/N

Notes: OK.

b) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)

Inspected Y/N Satisfactory Y/N

Notes: OK.

e) STAFF COMPETENCE & TRAINING

No of Staff 4 No Questioned 2

Inspected Y/N Satisfactory Y/N

Notes: Training records OK.

c) VAPOUR RECOVERY CONNECTIONS & SIGNS

Inspected Y/N Satisfactory Y/N

Notes: All OK.

Does the site have stage II vapour recovery? Y/N

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes: Very well managed site - no problems.

Are procedures in place adequate in the event of any leaks or spillages? Y/N

Notes:

Inspector S Whittinton Date 11/12/09

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.

Contract for the conduct of process permits: HDC & CCC