

3764 TESCO AMMANFORD  
PARK STREET  
AMMANFORD  
DYFED  
**SA18 2LR (PETROL STATION)**

Date: 4/10/09

## **RE: Vapour Recovery Inspection**

We have successfully carried out the Vapour Recovery Inspection on your site on Fri 02 Oct 2009 and hereby Issue the certificate for Inclusion into your Petrol Station Site Register.

The test was carried out by our trained technician and we can confirm that the following tests were carried out in accordance with IP/APEA blue book guidelines, Environmental Health and Petroleum Fire Authority recommendations.

**PV Valve Pressure**

**PASS**

**PV Valve Vacuum**

**PASS**

**Offset Fill Seal Test**

**PASS**

**VR System Integrity**

**PASS**

The date of your next inspection will be on or before Sat 02 Oct 2010



Lawrie Smail

Signed on behalf of Eurotank Environmental Ltd



**\*\*\* Test Certificate for Petroleum Vapour Recovery \*\*\***  
**Test Certificate No: 32202**

**Site Details**

<b>Site Name</b>	TESCO AMMANFORD
<b>Site Address:</b>	3764 TESCO AMMANFORD PARK STREET AMMANFORD DYFED

**\*\*\* Vapour Recovery Inspection Details \*\*\***  
**Units Inspected and Tested**

<b>Vapour Recovery Inspection Date:</b> Fri 02 Oct 2009	
Component	Test
<b>VISUAL:</b> Vapour recovery system Sound and Undamaged	<b>PASS</b>
Drain tap(if Fitted) Opened and Residue Removed	<b>N/A</b>
If No Drain tap manifold self draining	<b>PASS</b>
Remove, check and clean Flame Arrestor gauze and PV Valve	<b>PASS</b>
Check PV Valve Operating Correctly	<b>PASS</b>
Check Fill pipe Adaptors Seals fitted and Sealing	<b>PASS</b>
Check Vapour Recovery Adaptor Operating Correctly	<b>PASS</b>
Check vapour Recovery Adaptor Dust Cap seal	<b>PASS</b>
<b>Mandatory Signage Fitted and checked and clean</b>	
Tank No Grade Capacity labels fitted to Offset fills and in tank	<b>PASS</b>
"This tank is manifolded please disconnect before use" labels	<b>PASS</b>
"Max No of hoses to be connected at any one time" labels	<b>PASS</b>
"Connect Vapour Recovery hose First" label	<b>PASS</b>
Overfill Prevention Valves fitted warning label	<b>PASS</b>
<b>No</b> Overfill Prevention valves fitted warning label	<b>N/A</b>

**This Certificate of Vapour Recovery inspection was undertaken by a competent person employed by Eurotank Environmental Ltd and was carried out in accordance with IP/APEA guidelines, Environmental Health and Petroleum Fire Authority recommendations.**

**Signed By** Peter Smith  
 (Competent person carrying out the test)

**Dated:** 2/10/09