

## **Risk Assessment for Local Air Pollution Control**

Name of permitted activity:	Kleeman PL539	PG	Note:	PG3/1	6(12)	
Discussed with:	Philip Hales	LA Refe	rence:	B04/96	6	
Inspector's Name:	Claire Braybrook	Date: <u>31</u>		31/10/2	1/10/2019	
Operator Performance Ap	praisal					
Component 1 - Compliance Assess	sment					
Scale of Non-Compliance		Possi	ole Score	e	Scores Awarded	
A) Incident leading to justified complaint but no breach of specific permit condition or of general/residual BAT condition		0	points			
B) Incident leading to a justified com	plaint <sup>*</sup>	5 pe	r incident			
C) Breach of permit not leading to fo	rmal action	10 pe	er incident			
D) Incident leading to formal caution,	, Enforcement Notice or prosecution	15 pe	er incident			
E) Incident leading to a Prohibition N	otice	20 pe	er incident			
Гotal		(M	ax. 50)		0	
Unjustified complaints may be e.g. to inked to an incident at the process.	hose considered by the inspector to be unrea	asonable o	r which ca	nnot be o	clearly	
Where facility has been on Reduce	d Charge due to Mothballing or Reduced	Operating	Levels			
f) Failure to notify the regulator or restart or increase in level of operation to above the threshold requiring a permit at the installation in accordance with the acceptance letter			25			
Total (applies only when condition	F has been breached)	(1	/lax 75)			
Scoring for Component 2 - Assess	ment of Monitoring, Maintenance and Red	ords				
riterion		Possible Scores			Scores	
Sitterion		Yes	No	N/A	Awarded	
<ul><li>A) Are emissions monitored as requi Are emissions and emissions monitor</li></ul>	red in the permit? ring recorded as required in the permit?	0	<del>10</del>	0	0	
B) Monitoring requirements reduced compliance?	because results over time show consistent	0	0	0	0	
C) Is an appropriate maintenance sc	hedule in place and available on request?	0	5	0	0	
D) Fully documented and adhered permit?	to maintenance programme, in line with	0	5	Ф	0	
E) Full documented records as requi	red in permit available on-site?	0	5	0	0	
F) Has the operator notified the regu	lator promptly of all relocations of all plant?	<del>-5</del>	10	0	10	
Total score			(-5 to 35)		10	

Component 3 - Assessment of Management, Training and Responsibility					
Criterian	Possible Scores			Scores	
Criterion		No	N/A	Awarded	
(A) Are procedures in place to ensure proper management, supervision and training for process operations, proper use of equipment and effective preventative maintenance on all plant and equipment concerned with the control of emissions to air?	0	5	θ	0	
(B) Specific responsibilities assigned to individual staff for these procedures?	0	5	0	0	
(C) Does the operator maintain, and make available on request, a statement of training requirements for each operational post?	0	5	0	0	
(D) Are all staff with responsibility for operating the process sufficiently trained to be aware of their responsibilities under the permit, minimising emissions on start up and shut down and taking action to minimise emissions during abnormal conditions?	0	5	0	0	
(E) Trained staff on site throughout periods where potentially air-polluting activities take place?	0	5	θ	0	
(F) Is an 'appropriate' environmental management system in place?	-5	0	0	-5	
Total	(-5 to 25) -5		-5		
otal Score for Operator Performance Appraisal  Range -10 to 110 (135)		10	-5		

Overall scores	Score given
Operator Performance Appraisal	
Compliance Assessment	0
Assessment of Monitoring, Maintenance and Records	10
Assessment of Management, Training and Responsibility	-5
Total score	5

OVERALL SCORE FOR THE PROCESS	Range -10 to 110 (135)	5
REGULATORY EFFORT CATEGORY		
* high=score of >55, medium 30-55 and low <30	LOW, MED, HIGH	LOW

## Comments

Crusher not seen in operation this year. Discussed all crushers, procedures and record keeping. No changes since last inspection, daily emissions log and defect sheets maintained. Records seen and maintenance is by a traffic light system for servicing which is triggered by hours input. There is a defect reporting platform off R2C which is closely monitored and there is a sign off procedure for defects and service inspections. All crushers are fitted with a water suppression system and water cannons are used if required.

Score given for component 2(F) due to Complaint from Cambridgeshire City Council regarding no notification in June 2019.

Operatives are trained in the use of the plant and also have NPORS &/or CPCS. Mick George Ltd has ISO14001.