

Environmental permit inspection

Name of permitted activity: Henkel UK Ltd Permit: B19/93

Discussed with: Glenn Draper via Teams Reference: _____

Inspector's Name: Claire Braybrook Date: 30/03/2021

Reason for visit:	Check visit.		
Issues discussed:	<p>No problems on site since full Permit Inspection.</p> <p>Currently commissioning the new resin flow system. Pipework upgrading has been completed leading to a significant improvement in VOC emissions.</p> <p>No change to procedures, monitoring, training etc. No issues highlighted.</p>		
Conditions breached:	None		
<table border="1"> <tr> <td>Risk assessment revaluated?</td> <td>NO</td> </tr> </table>		Risk assessment revaluated?	NO
Risk assessment revaluated?	NO		