

**ENVIRONMENTAL PROTECTION  
REPORT – VAPOUR RECOVERY**

Premises PETER BOLOUGH SERVICES Person Seen JASAL  
Address 685 HADDON.

**OBSERVATIONS, ADVICE AND RECOMMENDATIONS:**

As a result of the inspection of your premises your attention is drawn to the following matters:

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS  
AND ASSOCIATED LOG BOOK**

Inspected Y/N Satisfactory Y/N

Notes:

LOG KEPT BUT NO  
ENTRIES.  
UNASSISTED DELIVERIES.

**b) TESTING CERTIFICATE FOR PRESSURE RELIEF  
VALVES**

Inspected Y/N Satisfactory Y/N

Notes:

2014 TEST DUE 2017

**c) LOG BOOK DETAILING MAINTENANCE,  
EXAMINATION & TESTING, INVENTORY  
CHECKING, INSTALLATION & REPAIR WORK  
(SITE REGISTER)**

Inspected Y/N Satisfactory Y/N

Notes:

SITE REGISTER

**d) STAFF COMPETENCE & TRAINING**

No of Staff 10 No Questioned 2

Inspected Y/N

Satisfactory Y/N

Notes:

**e) VAPOUR RECOVERY CONNECTIONS &  
SIGNS**

Inspected Y/N Satisfactory Y/N

Notes:

SIGN FADDED. BUT OTHERS  
OK.

Does the site have stage II vapour recovery? Y/N

Notes:

**f) SITE MANAGEMENT & OTHER COMMENTS**

Satisfactory Y/N

Notes:

Are procedures in place adequate in the event of any leaks  
or spillages? Y/N

Notes:

TRAINING OF STAFF COULD  
IMPROVE RECOVERIES.

Signed VPB.

Tel /Email 01954 284621  
alan.easey@cambridgeshire.gov.uk

Received by X [Signature]

Date/Time 21/2/2017

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.