

**ENVIRONMENTAL PROTECTION  
REPORT - VAPOUR RECOVERY**

Premises Peterborough Services Person Seen Mr Joseph Long  
Address anelle Road Peterborough

**OBSERVATIONS, ADVICE AND RECOMMENDATIONS:**

As a result of the inspection of your premises your attention is drawn to the following matters:

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS  
AND ASSOCIATED LOG BOOK**

Inspected Y/N Satisfactory Y/N

Notes:

No incidents

**b) TESTING CERTIFICATE FOR PRESSURE RELIEF  
VALVES**

Inspected Y/N Satisfactory ☒ Y/N

Notes:

Gas Environmental  
Services 30/11/2020

**c) LOG BOOK DETAILING MAINTENANCE,  
EXAMINATION & TESTING, INVENTORY  
CHECKING, INSTALLATION & REPAIR WORK  
(SITE REGISTER)**

Inspected ☒ Y/N Satisfactory ☒ Y/N

Notes:

**d) STAFF COMPETENCE & TRAINING**

No of Staff ☒ 17 No Questioned ☐

Inspected Y/N Satisfactory Y/N

Notes:

**e) VAPOUR RECOVERY CONNECTIONS &  
SIGNS**

Inspected Y/N Satisfactory Y/N

Notes:

Not inspected inside tank  
chambers. Offsets all ok

Does the site have stage II vapour recovery? ☒ Y/N

Notes:

**f) SITE MANAGEMENT & OTHER COMMENTS**

Satisfactory Y/N

Notes:

under new management

Are procedures in place adequate in the event of any leaks  
or spillages? Y/N

Notes:

Signed [Signature] H. SINGH

Tel / Email 01954 284 628

Received by [Signature]

Date/Time 23/8/2018 14:36

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.