

130771

# Environmental Protection Report – Vapour Recovery

Premises WICADAM SERVICE ST Person seen \_\_\_\_\_

Address 289 Broadway Valley PE 7 3NR

## OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection your attention is drawn to the following matters:

VR inspection conducted on behalf of the District Council

### a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK

Inspected Y / N

Satisfactory Y / N

Notes

Trk Taps not fitted

### b) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES

Inspected Y / N

Satisfactory Y / N

Notes

### c) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)

Inspected Y / N

Satisfactory Y / N

Notes

No incidents  
1/6/18 - Discussed requirements

### d) STAFF COMPETENCE & TRAINING

No of Staff ☐

No Questioned ☒

Inspected Y / N

Satisfactory Y / N

Notes

small set up

### e) VAPOUR RECOVERY CONNECTIONS & SIGNS

Inspected Y / N

Satisfactory Y / N

Notes

Does the site have stage II vapour recovery? Y / N

Notes

### f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y / N

Notes

Asked for DSGAR R.A  
to be forwarded

Are procedures in place adequate in the event of any leaks or spillages? Y / N

Notes

As per R.A

Signed [Signature]

Received by \_\_\_\_\_

Tel/Email: 01954 284628

Date/Time: 18/11/15

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.