

**ENVIRONMENTAL PROTECTION
REPORT - VAPOUR RECOVERY**

Premises Water Cabin

Person Seen Mr Tom Rowden

Address Great North Road Chesterton Peterborough PE7 2L5

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:
As a result of the inspection of your premises your attention is drawn to the following matters:
VR inspection conducted on behalf of Fenland Harborough District Council

a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK

Inspected Y/N Satisfactory Y/N

Notes:
one incident noted in 2018

b) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES

Inspected Y/N Satisfactory Y/N

Notes:
Ex 5 stage I tested 18/10/12
Weyre Dne 220 11/08/11 stage II
2 to be forwarded (less than 3 months)

c) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)

Inspected Y/N Satisfactory Y/N

Notes:

d) STAFF COMPETENCE & TRAINING

No of Staff 12 No Questioned

Inspected Y/N Satisfactory Y/N

Notes:
2 new staff yet to receive training
4 staff have had delivery training
11 have had formal training

e) VAPOUR RECOVERY CONNECTIONS & SIGNS

Inspected Y/N Satisfactory Y/N

Notes:

Does the site have stage II vapour recovery? Y/N

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes:
site register to be reviewed

Are procedures in place adequate in the event of any leaks or spillages? Y/N

Notes:

Signed [Signature]

Tel / Email 01954 7200678

Received by [Signature]

Date/Time 31/10/12

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.