

**ENVIRONMENTAL PROTECTION
REPORT - VAPOUR RECOVERY**

128870-1

Premises BP KATO CREW

Person Seen R. Hanson

Address A1 NORTH BOUNDS, CUCKSTON, CAMBS

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS
AND ASSOCIATED LOG BOOK**

Inspected Y/N

Satisfactory Y/N

Notes:

Site Register

**b) TESTING CERTIFICATE FOR PRESSURE RELIEF
VALVES**

Inspected Y/N

Satisfactory Y/N

Notes:

Stage 16 17/10/2013
+ Stage II

**c) LOG BOOK DETAILING MAINTENANCE,
EXAMINATION & TESTING, INVENTORY
CHECKING, INSTALLATION & REPAIR WORK
(SITE REGISTER)**

Inspected Y/N

Satisfactory Y/N

Notes:

ALL RECORDS AS
REQUIRED

d) STAFF COMPETENCE & TRAINING

No of Staff

9

No Questioned

1

Inspected Y/N

Satisfactory Y/N

Notes:

DDG Site Comp Pass
over 12 cases

**e) VAPOUR RECOVERY CONNECTIONS &
SIGNS**

Inspected Y/N

Satisfactory Y/N

Notes:

OFFSET ON
TANK TOP REQUIRE
CLEANING OFF

Does the site have stage II vapour recovery? Y/N:

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes:

Will Run Tidy Site

Are procedures in place adequate in the event of any leaks or spillages? Y/N:

Notes:

covered by emergency
procedures

Signed [Signature]

Tel /Email alan.easey@combustion-gas.co.uk
01454 284621

Received by [Signature]

Date/Time 17/9/2014

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.