ENVIRONMENTAL PROTECTION REPORT – VAPOUR RECOVERY

Premises BURTON BROTHERS	Person Seen L SHAW
Address BURT RD, RAMSET, PEZ 6 1 NE	
Address Doka to, Kareski, to a	
OBSERVATIONS, ADVICE AND RECOMMENDATIONS:	
As a result of the inspection of your premises your attention is drawn to the following matters:	
UR INSPECTION CARRIES OUT ON BEHALF OF HUNTS DC.	
a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK	b) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES
Inspected Y/N Satisfactory Y/N	Inspected Y/N Satisfactory Y/N
Notes: No INCIDENTS	Inspected Y/N Satisfactory Y/N Notes: OR TEST CERTIFICATE (
RECORDES	
c) LOG BOOK DETAILING MAINTENANCE,	d) STAFF COMPETENCE & TRAINING
EXAMINATION & TESTING, INVENTORY	No of Staff No Questioned
CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)	
Inspected Y/N Satisfactory Y/N	Inspected Y/N Satisfactory Y/N
Notes:	Notes: BASIC TRAINING
None RECORDED	DASIE TEACHER
	But SUFFICIENT FOR REDUREMENTS
	AL COUNT ON STATE OF THE
e) VAPOUR RECOVERY CONNECTIONS & SIGNS	f) SITE MANAGEMENT & OTHER COMMENTS
spected Y/N Satisfactory Y/N	Satisfactory Y/N
Notes: SIGNS REQUIRE	Notes: SITE REGISTER REQUIRES
CLEANING	TISTING RECTIFICATION
Coantrac	NOTICE ISSUES FOR MISSING
	CERTIFICATES.
Does the site have stage II vapour recovery? Y/N	Are procedures in place adequate in the event of any leaks or spillages? Y/N
Notes:	Notes: STAFF TRAINING
	MANUAL (SHELL)
Signed	Tel /Email 01954 284 641
eceived by Date/Time 14 10 15	
eceived by	Date/Time

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.