

**ENVIRONMENTAL PROTECTION
REPORT - VAPOUR RECOVERY**

Premises Barton Ditch Person Seen Mr T Clark
Address Bray Road Ramsey PE26 1NE

OBSERVATIONS, ADVICE AND RECOMMENDATIONS:

As a result of the inspection of your premises your attention is drawn to the following matters:

Inspection concluded on behalf of the District Council.

a) INCIDENTS OF VAPOUR LEAKS & LOCKS AND ASSOCIATED LOG BOOK

Inspected Y/N Satisfactory Y/N

Notes:

Nothing documented

b) TESTING CERTIFICATE FOR PRESSURE RELIEF VALVES

Inspected Y/N

Satisfactory Y/N

Notes:

9/11/2015 Failed on Vapour
connection Valve, Dist Cap
since rectified. TLM VR test
cert 317117

c) LOG BOOK DETAILING MAINTENANCE, EXAMINATION & TESTING, INVENTORY CHECKING, INSTALLATION & REPAIR WORK (SITE REGISTER)

Inspected Y/N

Satisfactory Y/N

Notes:

Nothing documented

d) STAFF COMPETENCE & TRAINING

No of Staff 10

No Questioned 1

Inspected Y/N

Satisfactory Y/N

Notes:

8 on list of competent persons.

e) VAPOUR RECOVERY CONNECTIONS & SIGNS

Inspected Y/N

Satisfactory Y/N

Notes:

only checked VR Tank 2 &
1. Please ensure all chambers
labelled Tanks no Back register VR as applicable.

Does the site have stage II vapour recovery? Y/N

Notes:

f) SITE MANAGEMENT & OTHER COMMENTS

Satisfactory Y/N

Notes:

Further to note 2 above

Are procedures in place adequate in the event of any leaks or spillages? Y/N

Notes:

no built

Signed [Signature]

Tel /Email [Signature]

Cambridgeshire - ECU - UK

Received by [Signature]

Date/Time 31/7/17 9.55

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.