

**ENVIRONMENTAL PROTECTION  
REPORT – VAPOUR RECOVERY**

Premises HKS Romsey

Person Seen W. Butler

Address \_\_\_\_\_

**OBSERVATIONS, ADVICE AND RECOMMENDATIONS:**

As a result of the inspection of your premises your attention is drawn to the following matters:

District council inspection conducted on 1st Feb 18

**a) INCIDENTS OF VAPOUR LEAKS & LOCKS  
AND ASSOCIATED LOG BOOK**

Inspected Y/N

Satisfactory Y/N

Notes:

**b) TESTING CERTIFICATE FOR PRESSURE RELIEF  
VALVES**

Inspected Y/N

Satisfactory Y/N

Notes:

**c) LOG BOOK DETAILING MAINTENANCE,  
EXAMINATION & TESTING, INVENTORY  
CHECKING, INSTALLATION & REPAIR WORK  
(SITE REGISTER)**

Inspected Y/N

Satisfactory Y/N

Notes:

**d) STAFF COMPETENCE & TRAINING**

No of Staff 5

No Questioned 1

Inspected Y/N

Satisfactory Y/N

Notes:

**e) VAPOUR RECOVERY CONNECTIONS &  
SIGNS**

Inspected Y/N

Satisfactory Y/N

Notes:

**f) SITE MANAGEMENT & OTHER COMMENTS**

Satisfactory Y/N

Notes:

Training records to be updated

Does the site have stage II vapour recovery? Y/N

Notes:

Are procedures in place adequate in the event of any leaks  
or spillages? Y/N

Notes:

Signed [Signature]

Tel /Email 01954 284 625

Received by [Signature]

Date/Time 1/1/18

This report only covers the areas inspected at the time of the inspection. It does not indicate compliance with any legislation.